

MATERIAL SAFETY DATA SHEET

Date last revised 9/11/08 By M. Lykins

MSDS-17

		& Synanyme: Lingar H		
		d Company Identification Trade Name & Synonyms: Linear High Density		
	Polyethylene, Champline, Sanalite			
High Density Polyethylene Chemical Family		Formula		
Linear High Density Polyethylene		(Ch2-ch2) n		
Proper DOT Shipping Name: N/A		DOT Hazard Classification: N/A		
Manufacturer: Quadrant EPP USA, Inc.		Chemtrec Phone Number		
2120 Fairmont Avenue.				
Reading, PA 19605		1-800-424-9300		
II. Ingredients				
Percent		Threshold Limit Value	OSHA PEL	
>99%		10 mg/m3	15 mg/m3	
III. Physical Data				
ing Point (Deg. F.) Specif		Specific Gravity (H20=1)		
N/A		0.96-0.97		
	Percent Volatile By Volume (%)			
Vapor Pressure (mm Hg) N/A				
Vapor Density (Air=1)		Evaporation Rate (Air =1)		
N/A		N/A		
Solubility in Water		рН		
Negligible		N/A		
Appearance & Odor				
IV. Hazard Identification/Fire & Explosion Hazard				
-D-1929 Met	hod B)(Setchk	in)		
Auto Ignition Temperature - >350°C (662° F.)				
_				
Flammable Limits LEL N/A N/A N				
	N/A			
Special Fire Fighting Procedures				
Firefighters should be equipped with positive pressure, self-contained breathing apparatus in enclosed area. NFPA Code: Fire 1, Health 1, Reactivity 0				
HMIS Code: Fire 1, Health 0, Reactivity 0				
s to avoid				
Unusual Fire & Explosion Hazards: Special conditions to avoid Dust is flammable and explosive when finely divided and suspended in air.				
	Percent >99% II. Physic fication/F I-D-1929 Met L e, self-container s to avoid	Ch2-ch2) n DOT Hazar Chemtrec P 1-800-424-9 II. Ingredients Percent >99% Specific Gra 0.96-0.97 Percent Vol Evaporation N/A pH N/A fication/Fire & Exp I-D-1929 Method B)(Setchk L	Ch2-ch2) n DOT Hazard Classification: N/A Chemtrec Phone Number 1-800-424-9300 II. Ingredients Percent	



MATERIAL SAFETY DATA SHEET

MSDS-17

V. Health Hazard Data				
rcinogen - NTP Program Carcinogen - IARC Program				
NO	NO NO			
Route of Exposure				
Eye contact				
Physical health Hazards:				
Dust may form explosive mixtures with air. Avoid dust formation and control ignition sources. Polyolefin dust particles suspended in air are combustible and may be explosive. Keep away from heat, sparks, flame, and other ignition sources. Prevent dust accumulations and dust clouds. Employ grounding, venting, and explosive relief provisions in accordance with accepted engineering practices and NFPA provisions in any process capable of generating dust and/or static electricity. Explosion hazards apply only to dusts, not granular forms of this product. See also Special Precautions section below.				
Signs and Symptoms of Acute Exposure:				
Molten polymer may cause thermal burns. At process temperatures, irritating fumes may cause soreness of the nose and throat. Mechanical irritation is possible.				
Primary Route(s) of Entry				
Inhalation of particulates.				
Emergency First Aid				
Inhalation: If symptoms are experienced, move victim to fresh air. If symptoms persist, obtain medical attention.				
Eye Contact: Wash eyes with clean, low pressure water. If irritation persists, seek medical advice.				
Skin Contact:				
Molten material. If molten material comes in contact with the skin, molten material from the skin. Get medical attention immediately.	cool under running water. Do not attempt to remove the			
VI. Reactivity Data				
STABILITY Unstable	Conditions To Avoid			
X Stable	None Known			
INCOMPATABILITY	Materials To Avoid			
Hazardous May Occur	Strong oxidizing agents.			
Polymerization X Will Not Occur	Conditions To Avoid			
	None Known			
Hazardous Decomposition Products: Aliphatic Hydrocarbons				
VII. Environmental Protection Procedures				
Spill ResponseSweep up for Disposal or reuse.				
Waste Disposal MethodIncineration or landfill - dispose of in accordance with Federal, State and Local regulations.				
VIII. Special Protection Information				
Eye Protection: Glasses with side shields.				
Skin Protection: When handling molten material protective clothing such as long sleeves or laboratory coat should be worn. Use				

Skin Protection: When handling molten material protective clothing such as long sleeves or laboratory coat should be worn. Use heat-resistant gloves, boots and face protection.

Respiratory Protection (Specific Type): NIOSH approved dust respirator recommended. If material is being burned wear an organic respirator.

Ventilation Recommended: Local ventilation in dusty conditions, or if thermal decomposition occurs.

Other Protection: Gloves and protective garments when handling molten material.

Handling: The handling of powder in both loading and unloading operations, as well as fabrication, may cause dust to be formed, and necessary precautions for personal protection (See Section VIII) should be used. As with all finely divided materials, precautions should be taken to avoid inhalation and eye contact.



MATERIAL SAFETY DATA SHEET

IX. Special Precautions/Information

Hygienic Practices In Handling & Storage: Wash with soap and water.

Precautions For Repair & Maintenance Of Contaminated Equipment: Eliminate ignition sources.

Transfer from storage with a minimum amount of dusting. Ground all transfer, blending, and dust collecting equipment to prevent static sparks in accordance with NFPA 70 "national Electric Code". Review and comply with all relevant NFPA provisions, including but not limited to NFPA 484 and NFPA 654 related to combustible dust hazards. Remove all ignition sources from material handling, transfer, and processing areas where dust may be present. Local exhaust ventilation should be provided in work area.

Other Precautions

Store in a sprinkler protected warehouse. Since High Density Polyethylene products are polyethylene they will burn with a hot flame if ignited. Avoid contact with ignition sources such as open flames. Keep a fire extinguisher near if welding is done in the area of High Density Polyethylene products. If a heat source is present, keep the area well ventilated.

X. Regulatory Information

OSHA Status: Polyethylene is not considered hazardous under OHSA.

TSCA Inventory Status: All ingredients are listed.

CERCLA Reportable Quantity (RQ): None

SARA Title III:

Section 302/304. No extremely hazardous substances

Section 311/312.No reporting requirements although it is suggested that storage of >10,000 lbs of polyethylene in one facility should be listed on a Tier II report.

Section 313: No reporting requirements.

XI. Warning Labels

CAUTION: Please consult the product MSDS sheet for important information.

NFPA Code: Fire 1, Health 1, Reactivity 0 HMIS Code: Fire 1, Health 0, Reactivity 0

Hazard data contained herein was obtained from raw material suppliers. The information presented is believed to be factual, as it was derived from the works and opinions of persons believed to be qualified. However, no facts contained in the information are to be taken as a warranty, or representation, for which Quadrant EPP USA, Inc. bears legal responsibility. The user should review any recommendation in the specific context of the intended use to determine if they are appropriate.

N.A.= Not Applicable N.E.= Not Established